

## IMPORTANT SAFETY RECALL

**This notice applies to your vehicle, VIN:**

**NHTSA Recall # 26V-412**

**Tiffin Recall # TIF-149**

August 26, 2026

### **MaxxAir Fan Printed Circuit Board May Overheat**

Dear Tiffin Motorhome Owner,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Tiffin Motorhomes has decided that a defect which relates to motor vehicle safety exists in the following models of motorhomes, **2026 and 2027 Allegro Bay Motorhomes, 2026 Allegro Breeze Motorhomes, 2026 and 2027 Allegro Bus motorhomes, 2026 and 2027 Allegro Open Road Motorhomes, 2026 and 2027 Allegro RED Motorhomes, 2026 Byway Motorhomes, 2026 and 2027 GT1 Motorhomes, 2026 Midas Motorhomes, 2026 & 2027 Open Trail Motorhomes, 2026 and 2027 Phaeton Motorhomes, 2026 and 2027 Wayfarer Motorhomes and 2026 and 2027 Zephyr Motorhomes built between January 12, 2026, and June 19, 2026.**

These motorhomes are equipped with the MaxxAir brand of roof vent fan. The printed circuit board installed in the fan has a safety defect that can result in the overheating of the printed circuit board. A printed circuit board that overheats may result in a fire.

The defective printed circuit boards will be replaced with updated printed circuit boards that do not contain the defect.

**To eliminate any chance of the MaxxAir vent fan overheating, RVP recommends that the fans not be operated until the recall repair is completed.**

Please arrange to take your motorhome to a ***reputable service center OR dealer of your choice*** to have the inspection and correction completed. A list of Tiffin Motorhomes authorized dealers is available online at <https://tiffinmotorhomes.com/service-center-locations>. The inspection of the vent fan may take up to 15 minutes per fan to complete. If a defective printed circuit board is found, please allow added time, up to 15 additional minutes per fan, to have the printed circuit board replaced. This work will be completed at no charge to you, the owner.

If you are using a service center that is not a Tiffin Motorhomes authorized repair facility, please make sure that they contact Tiffin Motorhomes or RVP for the work instructions. Tiffin Motorhomes service department may be reached by phone at 256-356-0261 or by email [service@tiffinmotorhomes.com](mailto:service@tiffinmotorhomes.com). For questions related to this recall, including questions about payment, reimbursement for work completed before the recall was issued, parts

or work instructions, please contact the RVP Service Department, 574-247-9235 option 1 or by email at [rvpsupport@airxcel.com](mailto:rvpsupport@airxcel.com).

You may be liable for any progressive damage that results from your failure to complete the recall within a reasonable time after receiving notification.

If you do not own the vehicle identified by the vehicle identification number appearing on this Recall Notification, please return the notification to the Tiffin Motorhomes Recall Department with any information you can give that will help us in finding the present owner. You may also send an email to [recalls@tiffinmotorhomes.com](mailto:recalls@tiffinmotorhomes.com).

If you are unable to have the defect remedied without charge and within a reasonable time after you tender the vehicle for repair, please contact the Tiffin Warranty Department, at 1-256-356-8661, 8:00 a.m. to 3:30 p.m., Central Time. You may also wish to notify the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC 20590, or phone 1-888-327-4236 (TTY: 1-888-275-9171): or go to <http://www.safercar.gov>.

**Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.**

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

Tiffin Motorhomes Compliance Department