

D127- FUEL TANK WALL THICKNESS CONCERN

SAFETY RECALL



AFFECTED MODELS	26MY Defender
VOLUME AFFECTED	6 US 2 CAN
CONCERN	A concern has been identified on certain vehicles where the fuel tank wall thickness is too low around the Inlet Check Valve(ICV) weld area. Insufficient material thickness in this area may lead to fuel tank cracking during vehicle operation. The fuel tanks will require replacement..
REPAIR TIME	Between 3 and 4 ½ hrs + DIDO
CAMPAIGN LAUNCH	Retailers were notified via admin bulletin on May 7th, 2026. Target date for repair bulletin launch is June 15th, 2026
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is available and completed. Please refer to recall bulletin for recommendations for any used vehicles in retailer inventory. All affected VINs are flagged in TOPIx and the warranty portal.