



# SAFETY RELATED RECALL

Global Recall Action  
Number: D082

<b>Subject:</b>  <b>Incorrect Certification Label</b>	Publication No.: D082
	Model: Range Rover Sport (L1)
	Model Year: 2026
	Date of Issue: 13 January 2026

<b>To:</b>	Jaguar Land Rover North America, LLC.
<b>For the Attention of:</b>	The approved JLR retailer / authorized repairer.
<b>Important:</b>	NOTE: The information in this campaign is intended for use by professional technicians. If you are not a JLR retailer / authorized repairer, do not assume that a condition described affects a specific vehicle. Contact an authorized JLR retailer / authorized repairer to determine if this campaign applies to a specific vehicle.

## FOR THE ATTENTION OF ALL:

### DESCRIPTION OF ISSUE AND THE EFFECT ON VEHICLE OPERATION

A concern has been identified on certain 2026 model year Range Rover Sport vehicles equipped with the AJ20 P6 engine where the incorrect mass is stated on the certification label. The mass on the certification label exceeds that certified by 200 Lbs.

Incorrect weight information on the certification label could lead to overloading of the vehicle and increase the risk of a crash.

### ACTION TO BE TAKEN

JLR has taken the decision to recall affected vehicles to repair the vehicle.

Following procedures appropriate to your market and as required by local legislation, owners of affected vehicles must be contacted requesting that the owner contact their nearest JLR retailer / authorized repairer as soon as possible to arrange for the repair to be completed. The National Sales Company (NSC), Importer, Regional Office or Government agency will contact the customers. If you have any questions about this process, contact your NSC / Importer or Regional Office for more information.

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

JLR retailers / authorized repairers are reminded that they must not sell vehicles identified as affected by this campaign until such time as the repair has been successfully completed.

An owner may indicate that a repair has already been completed for this concern, in which case the full cost of the repair should be reimbursed. Refer to the warranty section of this campaign for details of the Customer Reimbursement and Related Damage Process. At the time of confirming a booking for a vehicle repair, make sure you check the Warranty Portal to confirm if there are any other outstanding campaigns, to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

For information purposes, a Technical Question and Answer document is attached.

### FOR THE ATTENTION OF NORTH AMERICAN TERRITORIES ONLY:

National Highway Traffic Safety Administration (NHTSA) reference number: 26V-005

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your JLR retailer / authorized repairer. Unsold vehicles must be repaired prior to handover of the vehicle for retail sale.

	<b>The following applies to:</b> [Guam, Puerto Rico, United States, United States Minor Outlying Islands]
--	--

### REGULATORY INFORMATION



**The following applies to:**

[Guam, Puerto Rico, United States, United States Minor Outlying Islands]

Jaguar Land Rover North America, LLC have informed the National Highway Traffic Safety Administration (NHTSA) of their intent to perform a Safety Recall on certain 2026 model year Range Rover Sport vehicles imported into the United States markets. Information relating to this Safety Recall will be posted on the NHTSA website. United States Federal regulations require that JLR retailers / authorized repairers must be notified within a reasonable time after the manufacturer decides that a defect that relates to motor vehicle safety or a non-compliance exists. United States Federal Law requires JLR retailers / authorized repairers to complete any outstanding Safety Recall before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a JLR retailer / authorized repairer could result in a maximum civil penalty of up to the equivalent of \$27,874.00 USD per violation and the equivalent of \$139,356,994.00 USD for a related series of violations. This Safety Recall serves as notification to all JLR retailers / authorized repairers in the United States and Federalized Territories that any affected new vehicles may not be sold and delivered for customer use until the Safety Recall repair is completed.

**The following applies to:**

[Guam, Puerto Rico, United States, United States Minor Outlying Islands]

Jaguar Land Rover North America, LLC recommends that affected sales demonstrator and loaner vehicles are repaired before use, and that used vehicles are repaired before sale. JLR retailers / authorized repairers who proceed against this recommendation, where legally permitted, must clearly and conspicuously disclose the open Safety Recall notice to the applicable customers.

Yours faithfully

Steve Oldham

Global Customer Care Quality Director

## SERVICE INSTRUCTION - D082

### Parts Information

Certification labels will be provided free of charge.

### SROs

Description	SRO	Time
Certification label - Renew	05.10.10	0.1
Drive in / drive out	02.02.02	0.2

#### NOTE:

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPlx to obtain the latest repair time.

### Warranty Information

Warranty claims must be submitted quoting program code D082 with the relevant option code from the table below. As option codes are used there is no requirement for you to enter SROs or parts, these are included for information only.

Program	Option	Description	SRO	Time
D082	A	Certification label - Renew	05.10.10	0.1
D082	B	Certification label - Renew	05.10.10	0.1
		Drive in / drive out	02.02.02	0.2

#### NOTE:

The option that contains the drive in / drive out allowance may only be claimed when the vehicle has been brought back into the workshop for this action alone to be undertaken.

Warranty claims must be submitted in accordance with the current JLR Global Warranty Manual, and its amendments, unless stated otherwise in this campaign.

### Customer Reimbursement and Related Damage Process

#### NOTE:

If there is a requirement to claim for related / consequential damage or customer reimbursement, refer to the related instruction that can be found in TOPlx (in the Search box, search for 'Related Damage Claim' and open the related bulletin link).

## SERVICE INSTRUCTION

#### NOTES:

- Some variation in the illustrations may occur, but the essential information is always correct.
- Some components shown removed for clarity.

1. Open the drivers door.

01



2. Remove and discard the certification label.

- Clean the surrounding area.
- Remove the adhesive backing from the new certification label.
- Install the new certification label.

3. Close the drivers door.

## **SAMPLE CUSTOMER LETTER - FOR INFORMATION ONLY**

Name  
Address line 1  
Address line 2  
Address line 3  
Post Code

Vehicle Identification Number (VIN):  
Registration Number:  
Program Number: D082

Date: month/year

### **SAFETY RELATED RECALL - 2026 Model Year Range Rover Sport vehicles - Incorrect Certification Label**

Dear

JLR would like to advise you that during ongoing quality assessment of our product it has been identified that a possible safety related problem may occur on certain JLR vehicles within a specific production range. Read the information below, explaining the actions that we intend to take and what you must do.

#### **Why are we contacting you?**

A concern has been identified on certain 2026 model year Range Rover Sport vehicles equipped with the AJ20 P6 engine where the incorrect mass is stated on the certification label. The mass on the certification label exceeds that certified by 200 Lbs.

Incorrect weight information on the certification label could lead to overloading of the vehicle and increase the risk of a crash.

#### **What will your JLR retailer / authorized repairer do?**

At your visit, your preferred JLR retailer / authorized repairer will have the certification label replaced.

#### **How long will it take?**

The work on your vehicle will be completed as quickly and efficiently as possible in order to minimize inconvenience to you. Your JLR retailer / authorized repairer will be able to advise how long your vehicle will be required for when a booking is made.

#### **What we are asking you to do**

Contact your preferred JLR retailer / authorized repairer without delay. To book your vehicle in for this action, you will need to provide your JLR retailer / authorized repairer with the following details, which are at the beginning of this letter:

- The VIN for your vehicle
- Vehicle registration number of your vehicle.
- The Program Number for the action.

If you do not have a JLR retailer / authorized repairer, access [www.landrover.co.uk](http://www.landrover.co.uk) or [www.landrover.com](http://www.landrover.com) for contact details.

If you no longer own the vehicle, could you complete the 'Change of Ownership' slip attached to this letter, returning the slip to JLR immediately in the enclosed Freepost envelope. This will enable us to make contact and share this information with the new owner.

#### **If you have concerns**


If you experience any concerns relating to this Recall, contact the Service Manager at the JLR retailer / authorized repairer for assistance or contact the JLR Customer Experience Center on 0345 303 2303 or (enter phone number).

This bulletin is being issued in accordance with the legislative or industry requirements concerning vehicle defects. The authorities will closely monitor the response rate of this bulletin.

Treat this matter with the urgency it requires, JLR apologize for any inconvenience this bulletin may cause and thank you, in advance, for your co-operation.

Yours sincerely

Head of Business

<h1>Technical Questions And Answers</h1>	
<p>FOR USE ON ENQUIRY</p>	
<p>JLR D082</p>	
<p><b>Incorrect Certification Label</b></p>	

A concern has been identified on certain 2026 model year Range Rover Sport vehicles equipped with the AJ20 P6 engine where the incorrect mass is stated on the certification label. The mass on the certification label exceeds that certified by 200 Lbs.

**Question 1**

Who do I contact if a member of the press contacts me about this recall?

*Answer*

Make sure that any press enquiries are referred to the JLR Corporate Affairs office.

**Question 2**

Why is JLR recalling certain models

*Answer*

JLR is conducting a safety recall involving certain 2026 model year Range Rover Sport 3-liter Gasoline vehicles. Customers will be asked to take their vehicles to an approved repairer to have the certification label replaced.

**Question 3**

Can you tell me more about what is wrong with the vehicles?

*Answer*

The vehicle weight rating on the certification label exceeds that intended by 200 Lbs. This risks a customer overloading the vehicle.

**Question 4**

How would the customer become aware of potentially having this concern?

*Answer*

The weight on the certification label will not match that stated in the handbook.

**Question 5**

Does this concern affect vehicle safety?

*Answer*

Yes. If the vehicle is overloaded, it can lead to instability and increase the risk of a crash.

**Question 6**

Has JLR received many complaints?

*Answer*

JLR has not received any customer complaints of this concern.

**Question 7**

Have there been any accidents, injuries or fires?

*Answer*

There have been no reported accidents, injuries or fires as a result of this concern.

**Question 8**

Are there any precautions that can be taken to minimize the risk until the corrective measures are implemented?

*Answer*

Customers are advised to refer to the gross vehicle weight rating as listed in the handbook when loading their vehicles.

**Question 9**

How was the concern discovered?

*Answer*

The concern was identified through JLR's internal reporting process.

**Question 10**

How long has JLR known about this concern?

*Answer*

JLR became aware vehicles had entered into commerce in this condition on 6th January 2026.

**Question 11**

Is the concern leading you to any concerns regarding the reliability of the vehicle?

*Answer*

JLR has no concerns with the overall reliability of the vehicle. JLR carefully monitors field data to make sure that any matters relating to safety and compliance are rigorously investigated.

**Question 12**

What has JLR done in production

*Answer*

Production vehicles have had the correct weight written on the certification label.

**Question 13**

What will JLR retailers / authorized repairers do to the vehicles?

*Answer*

The vehicle will have the certification label replaced.

There will be no charge to the owners for this permanent repair.

**Question 14**

Which vehicles are affected by this concern?

*Answer*

2026 model year Range Rover Sport vehicles as below may be affected:

SAL1L9FU8TA615039 to SAL1P9EU6TA615529\*

\* Specific vehicles within the Vehicle Identification Number (VIN) range.

**Question 15**

Are other JLR models affected by these actions?

*Answer*

No JLR other models are known to be affected by this concern.

**Question 16**

Are parts available to rework vehicles?

*Answer*

Parts are available for JLR retailers / authorized repairers to conduct this repair.

**Question 17**

How much will the recall cost JLR?

*Answer*

Cost was not a factor in deciding to recall these vehicles.

**Question 18**

How do I know if my vehicle is affected?

*Answer*

All owners of potentially affected vehicles will shortly be contacted and invited to make an appointment with a JLR retailer / authorized repairer for the work to be completed.

In some countries, recall information is available online through the brand's web site.

Customers can use the Recall Search at <https://TOPIx.landrover.jlrext.com/TOPIx/vehicle/lookupForm>.

**Question 19**

How long does it take for the vehicle to be repaired?

*Answer*

The work will be completed out as quickly and efficiently as possible in order to minimize inconvenience to customers and is expected to take no longer than 18 minutes to complete. Naturally, due to JLR retailer / authorized repairer schedules, vehicles may be required for longer.

*Note:*

Make sure that any press enquiries are referred to the JLR Corporate Media office on +44-(0)2475-361000 or [jlrmedia@jaguarlandrover.com](mailto:jlrmedia@jaguarlandrover.com)