

## RECALL 26V154 & 2026-120 REMEDY INSTRUCTIONS



Make(s): ENTOURAGE  
Model(s): E1C320LVI & E1C320LVC  
Model Year(s): 2025 - 2026

Concern:  
The vehicle has 8 seatbelted positions whereas the Federal Placard indicates only 7 seatbelted positions. Therefore, any Cargo Carrying Capacity ("CCC") calculations may be incorrect.

Repair Code: RC-046-37-00-004816  
Allotted Time: .40 HRS.  
Inspection Code: N/A  
Allotted Time: N/A  
Photo(s) Required: NO  
Prior Authorization Required: NO  
Part(s) Kit Number: N/A  
Part(s) Return: N/A

Place vehicle in (P) Park and engage the Parking Brake. Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

STEP 1: LOCATE ONLY A SINGLE SEAT BELT ASSEMBLY IN THE REAR FACING DINETTE SEAT;

STEP 2: USING A 3/4" SOCKET AND RATCHET OR POWER TOOL, REMOVE THE BOLT(S) THAT ANCHOR THE SEAT BELT TO THE FLOOR;

- THIS SHOULD BE A TOTAL OF ONE SEAT BELT;
- THE VEHICLE SHOULD ONLY HAVE A TOTAL OF 7 (SEVEN) SEAT BELTED POSITIONS REMAINING;
  - 2 – DRIVER AND PASSANGER
  - 2 – THEATER SEATING
  - 3 – DINETTE BENCHES

STEP 3: CUT THE SEAT BELT(S) IN HALF AND DISCARD;

STEP 4: CLEAR WORKING AREA;

STEP 5: CLAIM REPAIR CODE.