

Recall Repair Instructions

NHTSA Recall # 26V-156

Tiffin Recall # TIF-147

Purpose: Replace incorrect OCCC label with a correct OCCC label.

Models Involved: 2025 and 2026 GH1 Motorhomes, 2025 and 2026 GT1 Motorhomes, and 2026 GH2 Motorhomes built between March 20, 2024, through March 12, 2026

FLAT RATE CODE & TIME ALLOWED *To file the warranty claim for payment, please use the following flat rate code.*

Involved and label corrected – 9890RC01 for 0.15 hours. No authorization is required for work completed at the flat rate times stated on the work instructions. Use **“TIF-147”** as the authorization on claim for payment.

Parts:

Isopropyl alcohol cleaner or wipe

OCCC label included with owner letter

Repair Instructions:

1. The yellow Cargo Carrying Capacity Label can be found on the passenger’s side door panel Figure 1.
2. Remove the old label and discard
3. Clean the passenger's side door jamb with isopropyl alcohol and carefully place the new label as shown

in Figure 2.



Figure 1




Figure 2