

## Recall Repair Instructions

NHTSA Recall # 26V-342

Transport Canada Recall # 2026-254

Tiffin Recall # WAY-107

**Purpose:** Replace the Incorrect OCCC Label with the correct OCCC Label.

**FLAT RATE CODE & TIME ALLOWED** *To file the warranty claim for payment, please use the following flat rate code.*

**Involved and label corrected - 8811RC01 for 0.25 hours. No additional authorization is required for work completed at the flat rate times stated on the work instructions. Use "WAY-107" as the authorization on claim for payment.**

### Parts:

Isopropyl alcohol cleaner or wipe

OCCC label included with notification letter

### Repair Instructions

1. The incorrect white Cargo Carrying Capacity Label can be found on the driver's side door panel, see Figure 1. The label can be left in the current position.
2. Clean a clear area of the passenger's side door jamb with isopropyl alcohol and carefully place the new label in a clear area of the door jamb. DO NOT cover up the yellow label already installed as it has different information listed.




Figure 1




Figure 2