

RECALL 26V398 / 2026-306 REMEDY INSTRUCTIONS		
 FOREST RIVER	Make(s): R. POD, NOBO & IBEX Model(s): MANY, SEE BELOW Model Year(s): 2025 - 2027	Repair Code: RC-003-09-00-004842 Allotted Time: .50 HRS. Inspection Code: RC-003-05-00-004841 Allotted Time: .10 HRS.
	Concern: The 110V circuits of the distribution panel may be mislabeled.	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: N/A Part(s) Return: N/A

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

CERTAIN 2025 – 2026 – IBEX: BXT16MBJ, BXT16MKD, BXT16MKS, BXT16MRJ, BXT16RKB, BXT19BRK, BXT19MBH, BXT19MSB, BXT19QRB, BXT20FKDS, BXT20MDS, BXT20MKB, BXT20MRK, BXT23MBH, BXT25MLB, BXT25RBH, BXT25RLSS & BXT26BRE

CERTAIN 2025 – 2026 – NOBO: NBT18.0, NBT18.1, NBT18.2, NBT18.3, NBT18.7, NBT19.0, NBT19.2, NBT19.3, NBT19.4, NBT19.6, NBT20.1, NBT20.2, NBT20.3, NBT20.4, NBT20.5, NBT20.6, NBT20.7, NBT20.8 & NBT20.9

CERTAIN 2025 – 2027 – R. POD: RPT150, RPT153, RPT171, RPT180, RPT185, RPT190, RPT192, RPT194, RPT194, RPT197, RPT198, RPT200, RPT202, RPT203, RPT204, RPT204, RPT205, RPT206 & RPT207

Remedy:

For WF-8735-AD-GE - 35 AMP CONVERTER, reference Figure 1.

For WF-8955-AD-GE - 55 AMP CONVERTER, reference Figure 2.

For WF-8930 - 50 AMP DISTRIBUTION CENTER, reference Figure 3.

STEP 1: TEST CIRCUITRY FOR ACCURACY OF THE LABELED 110V BREAKERS;

STEP 2: IF A 110V BREAKER(S) IS MISLABELED, REFERENCE THE APPROPRIATE “30AMP” OR “50AMP” LABELS ATTACHED;

STEP 3: PRINT AND APPLY THE CORRECT LABEL TO THE CORRECT 110V CIRCUIT(S);

- LABEL TEMPLATE 5162 TO PRINT LABELS FOR WF-8735-AD-GE - 35 AMP CONVERTER ONLY;
- LABEL TEMPLATE 8163 TO PRINT LABELS FOR WF-8955-AD-GE - 55 AMP CONVERTER;
- LABEL TEMPLATE 8163 TO PRINT LABELS FOR WF-8930 - 50 AMP DISTRIBUTION CENTER;

STEP 4: APPLY LABELS TO CONVERTOR OR DISTRIBUTION PANEL AS NEEDED TO CORRECTLY IDENTIFY 110V CURCUITS;

STEP 5: CLAIM REPAIR CODE WHEN COMPLETED.

RECALL 26V398 / 2026-306 REMEDY INSTRUCTIONS




Make(s): R. POD, NOBO & IBEX
Model(s): MANY, SEE BELOW
Model Year(s): 2025 - 2027

Concern:
The 110V circuits of the distribution panel may be mislabeled.

Repair Code: RC-003-09-00-004842
Allotted Time: .50 HRS.
Inspection Code: RC-003-05-00-004841
Allotted Time: .10 HRS.
Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: N/A
Part(s) Return: N/A

FIGURE 1 - WF-8735-AD-GE - 35 AMP CONVERTER



RECALL 26V398 / 2026-306 REMEDY INSTRUCTIONS




Make(s): R. POD, NOBO & IBEX
Model(s): MANY, SEE BELOW
Model Year(s): 2025 - 2027

Concern:
The 110V circuits of the distribution panel may be mislabeled.

Repair Code: RC-003-09-00-004842
Allotted Time: .50 HRS.
Inspection Code: RC-003-05-00-004841
Allotted Time: .10 HRS.
Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: N/A
Part(s) Return: N/A

FIGURE 2 - WF-8955-AD-GE - 55 AMP CONVERTER



RECALL 26V398 / 2026-306 REMEDY INSTRUCTIONS



Make(s): R. POD, NOBO & IBEX
Model(s): MANY, SEE BELOW
Model Year(s): 2025 - 2027

Concern:
The 110V circuits of the distribution panel may be mislabeled.

Repair Code: RC-003-09-00-004842
Allotted Time: .50 HRS.
Inspection Code: RC-003-05-00-004841
Allotted Time: .10 HRS.
Photo(s) Required: NO
Prior Authorization Required: YES
Part(s) Kit Number: N/A
Part(s) Return: N/A

FIGURE 3 - WF-8930 - 50 AMP DISTRIBUTION CENTER

