

		Tesla, Inc. Service Bulletin		<i>Repurchase Vehicle or Rescind Letter of Compliance</i>	
SB-26-00-004 July 16, 2026					
Classification		Section/Group	Mobile Service	Configuration	
Recall Bulletin		00 - Inspection & Service	N/A	N/A	
Model	Model Year	Country/Region	Build Location		
Model 3	2024	United States	Giga Shanghai, Giga Berlin		
Model Y	2026				
The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.					

Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Certain Model 3 and Model Y vehicles manufactured for the Canadian market might have been imported by customers into the United States. These vehicles are noncompliant with United States Federal Motor Vehicle Safety Standards (FMVSS) 201 and FMVSS 208.

Correction

Tesla will proactively reach out to affected customers. Vehicles imported into the United States and currently registered in the United States will be repurchased by Tesla. Vehicles not yet imported and registered in the United States will have their letters of compliance rescinded and replaced with letters that explain their vehicle is noncompliant to certain FMVSS. These vehicles cannot be imported by customers into the United States under 49 CFR Part 591.5(g).

Correction Description	Correction	Time
Contact Customer; Repurchase Vehicle	S012600004	0.00
Contact Customer; Rescind Compliance Letter	S022600004	0.00

Procedure

Tesla Service Campaigns and Business Resolution teams will interface with owners of the affected vehicles and apply the appropriate correction code as needed.