

Recall Campaign Bulletin



September 2026

TO: ALL MERCEDES-BENZ DEALERS

CAMPAIGN NO.	2026080004
CAMPAIGN DESC.	26P7291007
NHTSA ID	26V481
SUBJECT	Corrosion on Door-Lock Microswitch
MODEL(S)	GLB (247 platform)
MODEL YEAR(S)	2021 – 2026
CAMPAIGN POPULATION	3504

Campaign Technical Instructions

Prior to performing this Campaign:

Check the Vehicle Master Inquiry (VMI) to verify this campaign applies to the specific vehicle.

1. Always check for other open campaigns and perform them accordingly!
2. Review the entire campaign bulletin first, and perform the procedures exactly as described.

Order No. P-RC-2026080004

Recall Campaign Bulletin

Model(s): 247

Primary Parts Information:

Qty.	Part Name	Part Number
1	Drivers Door Lock	**A0997203702 or A0997201703
2	Countersunk bolt with hexalobular socket (door lock)	*
1	Pan head screw with hexalobular socket (door lock)	*

* The replacement parts should be determined in Xentry Parts Information using the vehicle identification number.
** Both part numbers will work for the replacement of the door lock. Order whichever one is available. It is possible that a door lock from “Kieckert” or “Magna” can be installed.

 Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list, but may be claimed as needed. The required small parts are taken into account in the budgeting.

Work Procedure:

- 1. Replace driver’s door lock.

 For basic data of model 247, see AR72.10-P-4011MFC.



Model(s): 247

Warranty Information:

 **Note:** *The following allowable labor operation should be used when submitting a warranty claim for this repair:*

Damage Code	Operation Number	Description	Labor Time (hrs.)
72-910-07	11-0160	Replace driver's door lock	1.2

 **Note:** *Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change, and updates may not be reflected in this document.*