

Recall Campaign Bulletin



October 2026

TO: ALL MERCEDES-BENZ DEALERS

CAMPAIGN NO.	2026100001
CAMPAIGN DESC.	26P9190323
NHTSA ID	26V636
SUBJECT	Check Driver's Seatbelt Anchorage
MODEL(S)	CLA (178 platform)
MODEL YEAR(S)	2027
CAMPAIGN POPULATION	4

Campaign Technical Instructions

Prior to performing this Campaign:

Check the Vehicle Master Inquiry (VMI) to verify this campaign applies to the specific vehicle.

1. Always check for other open campaigns and perform them accordingly!
2. Review the entire campaign bulletin first, and perform the procedures exactly as described.

Order No. P-RC-2026100001

Recall Campaign Bulletin

Check/Test Procedure:

1. Remove exterior trim on seat frame (1, Illustration 1).

i For basic information on **vehicles with code 275**, see **AR91.10-P-1201CLB**.
Only the **trim** is removed (1, illustration 1).




Illustration 1: Shown with code 275

2. Check seat belt end fitting (3, illustration 3) for correct installation.
i Seat belt end fitting (3, illustration 3) must be installed **correctly**.
i For basic information, see AR91.40-P-1030-02CLA.




Illustration 3

- a. Seat belt end fitting (3, illustration 3) is **not** connected to seat belt end-fitting tensioner (4, illustration 3) and **not correctly** installed:



Carry out **work procedure**.

- b. Seat belt end fitting (3, illustration 3) is **correctly** connected to seat belt end-fitting tensioner (4, illustration 3) and **correctly** installed:



End measure.

Work Procedure:

1. Install seat belt end fitting correctly (Illustration 3).

i For basic information, see **AR91.40-P-1030-02CLA**.

2. Assemble in reverse order

Warranty Information:

 **Note:** The following allowable labor operation should be used when submitting a warranty claim for this repair:

Damage Code	Operation Number	Description	Labor Time (hrs.)
91 903 23	11-0182	Operations: Check seat belt end fitting on left front seat belt Includes: Remove/install trim	0.2
	11-0183	Operations: Correctly install seat belt end fitting on left front seat belt (after check)	0.1

 **Note:** Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.