



July, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2020 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number 26C18 - Second Row Left-Hand and Right-Hand Seat Belt Retractor Floor Bolt
and Description: Inspection

What is the issue? Your vehicle may have been produced with loose or missing second row left-hand or right-hand seat belt retractor anchor bolts to the floor.

An improperly secured seat belt retractor may inadequately restrain an occupant in a crash, increasing the risk of injury. You may also notice a rattle noise caused by a lower anchor that is not properly secured.

If you have questions or concerns, please contact our **Lincoln Recall Assistance Center (RAC)** at **1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Julio de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

Según nuestros registros, no se realizaron en sur 2020 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 26C18 - Inspección del tornillo al piso del retractor del cinturón de seguridad de la segunda fila

¿Cuál es el problema? Es posible que su vehículo haya sido fabricado con tornillos de anclaje del retractor del cinturón de seguridad de la segunda fila, ya sea del lado izquierdo o del derecho, sueltos o faltantes.

Un retractor del cinturón de seguridad mal colocado puede proteger inadecuadamente a un ocupante en un choque, lo cual aumenta el riesgo de sufrir lesiones. También es posible que perciba un ruido de traqueteo causado por un anclaje inferior que no está bien sujeto.

Si tiene preguntas o inquietudes, comuníquese con nuestro **Centro de asistencia de campañas (RAC)** **Lincoln al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es es.Lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.



L I N C O L N

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0255395 A / 000000000000651 / 43



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

