



Service Bulletin

American Honda Motor Co., Inc.

CB1000SP #3
March 2026

SAFETY RECALL

2025 CB1000SP DISCONNECTED FUEL FEED HOSE

BACKGROUND

Honda is issuing a **STOP SALE NOTICE** on **CERTAIN 2025 CB1000SP** motorcycles. Due to a manufacturing assembly error, the fuel feed hose connected to the fuel tank may unexpectedly come off during operation, resulting in engine stalling and fuel leakage, potentially increasing the risk of a crash or injury.

AFFECTED UNITS

As of March 20, 2026, you **MUST NOT SELL ANY NEW or USED** 2025 CB1000SP motorcycles until it is repaired according to a forthcoming Service Bulletin.

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information on iN*, available March 24, 2026.
- To manage your affected new inventory, use your dealer *eResponsibility Report on iN*, available March 24, 2026.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected motorcycles in late May 2026. Customers will be informed that their motorcycle is affected by this safety-related defect and to make an appointment with an authorized Honda dealer to have their unit repaired.

PARTS AVAILABILITY

Repair parts are currently unavailable. Once available, this service bulletin will be revised and dealers will be notified by *iN* message.

DEALER REPAIR RESPONSIBILITY

- Repairs must be performed by a qualified technician.
- Performing this repair exactly as shown in Repair Procedure instructions is critical for the remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this repair was properly performed.

1 of 1