

		CURT® TOURING COIL SUSPENSION (TCS) SHOCK BOLT INSPECTION		0	4 3 2 1 0 Difficulty Level
RECALL:	900012 REC-2602 CURT®Touring Coil Suspension (TCS) Shock Bolt Inspection				
PRODUCT:	Model Z	VIN Range:	Any unit (production or aftermarket) with TCS installed up to VIN #013017	REVISION:	REV-B
DATE:	June 2, 2026				

NOTE: THIS DOCUMENT IS ONLY INTENDED TO ENSURE THAT YOUR UNIT IS SAFE TO TOW TO A DEALER / SERVICE CENTER TO HAVE THE RECALL WORK COMPLETED. THE RECALL WORK (REPLACEMENT OF ALL SIXTEEN [16] BOLTS) MUST STILL BE COMPLETED.

Applies To:

This document refers to any Brinkley Model Z Fifth Wheel built with a VIN of 013017 or earlier, that has a CURT®Touring Coil Suspension (TCS) System installed (either from the factory or Aftermarket). This document give instructions on how to inspect your system to ensure that all shock fasteners are present and your unit is safe to tow to a dealer or service center to have the recall work completed.

Inspection:

Refer to the image below for the inspection points. There should be four (4) fasteners present on each set of shocks on the TCS system (a total of sixteen [16]). There will be one (1) at the top of each shock (Figure 1A, 1B), and one (1) at the bottom of each shock (Figure 1C, 1D). There are two (2) shocks per set, and four (4) sets of shocks in the system.



Figure 1

If all fasteners are present, your unit is safe to tow to a dealer or service center to have the recall work completed. If any of the fasteners are missing or broken, stop towing your unit and contact Brinkley Customer Care immediately.

BRINKLEY CUSTOMER CARE:

phone: 888.502.3460 or 574.501.4280

email: CustomerCare@BrinkleyRV.com