

D145 – REAR VIEW CAMERA

- **Affected Vehicles:**
 - Certain 2021 to 2025 Land Rover Discovery Vehicles.
- **Concern and Repair:**
 - The water management system in the tailgate of the vehicle may not be sufficient to allow water to drain away from the rear view camera. This can allow water to pool around the camera installation and overtime can cause damage to the camera.
 - Technicians are to modify the camera housing to improve water drainage. **The functionality of the rear camera is also to be verified, if required, it will be replaced.**
- **Warranty Guidance:**
 - There is no requirement to enter the SRO's or parts as this will populate.
 - Claims can be submitted using code D145 and can be submitted using option code A or B.
- **Customer Reimbursement and Related Damage Process:**
 - If a new rear camera is required, it must be claimed through related damage process under campaign code D145.
 - Evidence of the rear view camera fault (photographs where necessary).
 - Make sure to provide the Vehicle Identification Number (VIN).