

D145 – REAR VIEW CAMERA

SAFETY RECALL



AFFECTED MODELS	21-25MY Discovery
VOLUME AFFECTED	15535 US 1020 CAN
REPAIR	On certain vehicles the water management system in the tailgate of the vehicle may not be sufficient to allow water to drain away from the rear-view camera. This can allow water to pool around the camera installation and overtime can cause damage to the camera. Technicians are to modify the camera housing to improve water drainage. The functionality of the rear camera will also be confirmed.
REPAIR TIME	0.1 hr + DIDO
CAMPAIGN LAUNCH	July 30th, 2026
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is available and completed. Please refer to recall bulletin for instructions on used vehicles in retailer inventory. All affected VINs are flagged in TOPIx and the warranty portal and are also flagged in BBSS inventory reports.