

# STOP SALE NOTICE



FOREST RIVER

SERVICE CAMPAIGN: 001277

FOREST RIVER ID: 83-2039

March 5, 2026

---

## **Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B**

“It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law.”

## **CANADA: Pursuant to the Canadian Motor Vehicle Safety Act, section 5**

*Companies who sell new non-complying vehicles may be in violation of the Motor Vehicle Safety Act. Substantial penalties apply to violations of this law. This notice is being sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.*

Pursuant to Federal Motor Vehicle Safety Act; 49 CFR Part 573.11; this notice shall serve as a formal

## **SAFETY RECALL - STOP SALE NOTIFICATION**

**CERTAIN 2026 IMPRESSION MPF235RW, MPF301ML, MPF315MB, MPF318RL, MPF360MYR, MPF36BR3 & MPF44STAY**

**DESIGNATED DATE RANGE: 1/06/2026 THROUGH 2/27/2026**

Please access your Home Page on Dealer Connect to verify if your Dealership has units in stock that are subject to this recall. Enter the Service Campaign number referenced above in the “Campaign Search” field, click on the “Campaign ID Number”. Next, select “MY VINS”. Not all Dealers have units in stock that are affected by this recall.

Forest River has decided that a safety defect exists in certain 2026 Impression Fifth Wheel Recreational Vehicles. Forest River is recalling the defect model(s) to ensure the safety of our future retail consumers and your dealership. Forest River is issuing a Stop Sale Notice effective immediately.

### **WHAT IS THE DEFECT**

The wire sheathing may allow conductors to not make adequate contact with the lugs in the 50AMP inlet.

### **EVALUATION OF RISK:**

Improper sheathing removal can expose conductors, allowing electrical arcing that may lead to fire and property damage.

### **SERVICE PROCEDURE:**

The remedy for this recall is under development. A second notice will be issued once the remedy is available.

### **HELPFUL CONTACT INFORMATION:**

CONTACT	PHONE
CUSTOMER SERVICE	(574) 327-2716