

10000768



Service Bulletin

File In Section: 08 - Body and Accessories

Bulletin No.: 02-08-44-019

Date: December, 2002



SERVICE MANUAL UPDATE

Subject: Revised Audio System Diagnostics**Models:** 1998-2000 Chevrolet Camaro
1998-2000 Pontiac Firebird

This bulletin is being issued to revise several audio system diagnostics in the Entertainment sub-section of the Service Manual. Please replace the current information in the Service Manual with the following information.

The following information has been updated within SI. If you are using a paper version of this Service Manual, please make a reference to this bulletin on the affected page.

Diagnostic Title	Step Effected	What Changed
Speakers Inoperative - One or More (No Sound, Radio Operates Normally) SI Document IDs #472778 and #415323	3	The following information was added to this step: Verify power and ground circuit voltages are present at the amplifier by measuring between the appropriate terminals on the amplifier connector.
Speakers Inoperative - One or More (General) SI Document IDs #448931 and #327342		
Speakers Inoperative - One or More (No Sound, Radio Operates Normally) SI Document ID #583214	4	
Speakers Inoperative - One or More (General W53, W54, W55, UQ0) SI Document ID #583211		

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION

10000768