

SERVICE INFORMATION BULLETIN

Subject:
CORRECTION IN WORKSHOP MANUAL FOR TIGHTENING TORQUE OF THE INJECTOR CLAMP BOLT

The document is to inform the dealers about the correction in the workshop manual listed below. Moreover, to announce that this service data be attached to the relevant pages of the workshop manuals

1. RELEVANT WORKSHOP MANUALS:

	Pub. No.		Page on the workshop manual
	U.S.A.	CANADA	
2008MY	S5-UJ05E04A	S5-CJ05E04A	EN07- 3
	S5-UJ05E04B	S5-CJ05E04B	

2. CONTENTS:

The tables in the respective manuals and pages shown above are incorrect. Please replace the incorrect tables.


Refer to page 2/2 for details.

SERVICE INFORMATION BULLETIN

FUEL SYSTEM (J05D)

EN07-3

COMPONENT LOCATOR



1 Injector	3 Bearing holder
2 Supply pump	4 Common rail

Tightening torque Unit: N·m {kgf·cm, lbf·ft}

A 12.3 {126, 9}	C 26 {250, 18}
B 39.2-49 {400-499, 29-36}	D 49-58.8 {500-599, 37-43}