

PAGES 1 TO 4 ARE PROTECTED BY  
COPYRIGHT AND HAVE BEEN  
PURPOSELY OMITTED



MONACO  
COACH CORPORATION

April 22, 2008

Re: Cummins Engine Warning Light

Dear Monaco Coach Owner:

As a courtesy to our customers, Monaco is continuously working to provide the best product available and to maintain a high level of commitment to customer satisfaction. We are sending this letter to ensure the integrity of your Monaco Coach Corporation product, as well as to encourage a lasting relationship with our corporation.

Monaco Coach Corporation is distributing Technical Service Information Bulletin #173 for certain 2007 Monaco Cayman, Diplomat, Knight & LaPalma Diesel and 2007 Holiday Rambler Ambassador, Endeavor, Neptune & Vacationer Diesel Class A Motorhomes. This bulletin concerns the Cummins engine Warning light wiring. The reconfiguration of the wires in the Cummins engine electrical harness plug may be required to allow the engine Warning light to function properly.

Our records indicate that you own one of the potentially affected motorhomes. Please schedule an appointment at your nearest dealer or repair facility to have TSI 173 performed at no cost to you. To better serve you, all Monaco Coach Corporation dealers have been provided with this Technical Service Information Bulletin in advance.

Thank you for allowing Monaco Coach Corporation to be a constant partner in your recreational needs. If you have any questions, please feel free to contact any member of the Technical Support Staff at (877) 466-6226. We are happy to assist you and ensure your continued satisfaction.

Sincerely,

Chuck R. Zucker  
Technical Coordinator Supervisor  
Monaco Coach Corporation

crz/kd

MONACO COACH CORPORATION  
91320 Coburg Industrial Way, Coburg, OR 97408  
Telephone: (541) 686-8011 • (877) 4-MONACO