

PAGES 1 THRU 5 ARE PROTECTED
BY COPYRIGHT AND HAVE BEEN
PURPOSELY OMITTED

10025325



MONACO
COACH CORPORATION

June 20, 2008

Re: Charge Air Cooler Fan Speed Relay Wiring

Dear Monaco Coach Owner:

As a courtesy to our customers, Monaco is continuously working to provide the best product available and to maintain a high level of commitment to customer satisfaction. We are sending this letter to ensure the integrity of your Monaco Coach Corporation product, as well as to encourage your lifelong relationship with our corporation.

Monaco Coach Corporation has determined the fan speed control relay for the charge air cooler may be wired incorrectly causing the fan speed control relay to stay engaged with the ignition off. As a result Monaco Coach Corporation is distributing Technical Service Information Bulletin #176 for certain Monaco Dynasty Class A Motorhomes built with Cummins ISM diesel engines between November 12, 2007 and April 11, 2008 (coach numbers 606910 through 607146). Rewiring of the charge air cooler fan speed control relay may be necessary to reduce the possibility of excessive battery drainage.

Our records indicate that you own one of the potentially affected motorhomes. Please schedule an appointment at your nearest dealer or repair facility to have TSI #176 performed at no cost to you. To better serve you, all Monaco Coach Corporation dealers have been provided with this Technical Service Information Bulletin in advance.

Thank you for allowing Monaco Coach Corporation to be a constant partner in your recreational needs. If you have any questions, please feel free to contact any member of the Technical Support Staff at (877)466-6226. We are happy to assist you and ensure your continued satisfaction.

Sincerely,

Chuck R. Zucker
Technical Coordinator Supervisor
Monaco Coach Corporation

crz/kd

MONACO COACH CORPORATION
606 Nelson's Parkway • P.O. Box 465 • Wakarusa, IN 46573
Telephone: (574) 862-7211 • (877)4-MONACO