

CSC-10026729-3697

September 17, 2008

SUBJECT: FIELD REPAIR #808-4
HENDRICKSON PUSHER AXLE BRAKE ASSEMBLY
EXPIRATION DATE: September 12, 2009

VIN: _____

Dear Peterbilt Customer:


This letter is to inform you of an issue with under-torqued brake assembly mounting bolts on a vehicle equipped with Hendrickson 8,000 LB pusher axle(s) identified by the VIN above. Failure to perform this repair could cause premature mounting bolt failure, resulting in reduced braking performance. Peterbilt is issuing this Field Repair to correct this condition.

<i>The problem is</i>	Under-torqued pusher axle brake assembly bolts
<i>What your dealer will do . . .</i>	Inspect and repair the brake assembly bolts

Please contact your Peterbilt dealership to schedule an appointment to perform this inspection, and repair if required. Inspection and repair will take up to four hours, and will be performed at no charge to you. This program is valid through the expiration date shown above.

If you require further information about this field repair program, or experience any difficulty in making arrangements for the repair, please contact: Peterbilt Motors Company, 1700 Woodbrook Street, Denton, Texas 76205: Customer Service Department, phone 940-591-4173.

Sincerely,



Rick Wood
Customer Service Manager