

CSC-10026734-5234

Involved: 796  
Repaired: 465



*Tiffin Motorhomes, Inc.*  
105 2<sup>nd</sup> St. NW  
Red Bay, AL 35582  
256-356-8661

### **SB-21 Switch Box Grounding Lug**

March 18, 2008

Dear Tiffin Customer/Dealer:

It has come to our attention that there is a potential problem with the switch box grounding lug. It is possible that the tap screw is not tight enough. This could cause problems at the load center causing a loss of ground. The remedy is to check the lug with a flat head screw driver. Make sure the tap screw is tight. We are allowing 15 minutes for the check and repair. We are enclosing pictures of the possible locations of the tap screw. However, note that this lug will be no further than 3 feet from your switch box. Thank you for your co-operation.

Please have the repairer to fill out the form at the bottom and send it along with an invoice (or a warranty claim if our dealer). We will then reimburse them. If you have to make the payment yourself, please fill out the form with a note that you paid for it and we will reimburse you.

VIN \_\_\_\_\_

Dealer or Service Center Name & Address \_\_\_\_\_  
\_\_\_\_\_

Invoice # \_\_\_\_\_ Date \_\_\_\_\_

\_\_\_\_\_ Pay to Dealer or Service Center

\_\_\_\_\_ Pay to Owner (Please include address if different from label above)







