
Reference	SSM40913
Models	XF / X250 XJ / X350 XK / X150
Title	XF, XK & XJ - Engine-Compartment Lid Ajar Switch
Category	Body
Last modified	06-Apr-2009 00:00:00
Symptom	112000 Latches/Locks & Security
Attachments	
Content	<p><u>Issue:</u> On investigation of warranty returns it has been noted that the engine-compartment lid latch has been lubricated.</p> <p><u>Cause:</u> Lubricant applied to the engine-compartment lid latch during routine servicing or for any other reason will, over time, migrate into the ajar switch and cause damage to the switch.</p> <p><u>Action:</u> DO NOT lubricate the engine-compartment lid latch as this may cause damage to the ajar switch, which may result in a rejected warranty claim for the latch.</p>