

CSC-10034709-9265

October 22, 2010

SUBJECT: Peterbilt Field Repair Notice #810-1
Odometer Accuracy
The affected VIN's are shown on the opposite side of this page
EXPIRATION DATE: October 29, 2011

Dear Peterbilt Customer:

Certain vehicles built between December 4, 2009 and August 17, 2010 were manufactured with defective instrumentation software. The software defect may intermittently result in an odometer that does not advance while the vehicle travels.


Peterbilt Motors Company has issued this Field Repair to install new software to correct this condition. This letter is to inform you that the vehicle(s) represented by the VIN number(s) in this letter are eligible for this Field Repair.

<i>The problem is...</i>	Inaccurate odometer display
<i>What your dealer will do...</i>	Install new software
<i>What you must do ...</i>	Contact your Peterbilt Dealer to schedule an appointment for repair

We encourage you to make an appointment with your nearest Peterbilt Dealer as soon as possible to schedule this repair. This repair will take about an hour, and will be performed at no cost to you.

We apologize for the inconvenience this may cause, and appreciate your cooperation in this matter.

Sincerely,



Rick Wood
Customer Service Manager