



Navistar, Inc.
4201 Winfield Road
Warrenville, IL 60555 USA

navistar.com



A NAVISTAR COMPANY

MAILED

DEC 10 2010

AUTHORIZED FIELD CHANGE G-10921

Compliance Dept.

DECEMBER 2010

Dear INTERNATIONAL® Customer,

Navistar has decided to perform an authorized field change campaign on certain 5900, 7600, 8600, and ProStar model trucks built 5/27/10 thru 9/15/10 with a MaxxForce 13 engine equipped with a 4-tab style oil filter.

If you own this vehicle, inspect the engine oil filter housing cover. The picture below is of the correct cover. Notice the center circular section is indented.

REASON FOR THIS CAMPAIGN

The suspect vehicles may have been built with an engine having a discontinued oil filter design. The replacement oil filter does not fit properly in the housing for the discontinued filter possibly allowing oil to by-pass the filter.



**Correct Oil Filter
Housing**

**No Repair
Required**

DESCRIPTION OF REPAIR


The repair will involve the customer inspecting the engine oil filter housing cover to determine if a repair is required. If a repair is necessary, a dealer will install a new engine filter housing and filter. Dealers have parts and instructions to repair your vehicle. The repair will be performed free of charge within the warranty period or one year from the date of this letter, whichever comes later and take approximately 60 minutes to complete.

If your vehicle is equipped with the correct housing, no repair is needed. Please call any INTERNATIONAL® dealer and ask them to submit an "Inspected - No Corrections Necessary" claim against your VIN for campaign 10921. This will update the records so that you will not be contacted again about this campaign. You can find your nearest dealer by calling 1-800-448-7825 or by using the dealer locator at <http://www.internationaltrucks.com>.

ACTIONS YOU SHOULD TAKE

Navistar's records indicate that you own a vehicle involved in this campaign. The vehicle is identified on the enclosed card.

The picture below is of the incorrect oil filter housing cover. Notice that the center circular section protrudes outward.



**Incorrect Oil Filter
Housing**

Repair Required

If your vehicle is equipped with the incorrect housing, please schedule an appointment with any INTERNATIONAL® dealer to have your vehicle repaired. You can find your nearest dealer by calling 1-800-448-7825 or by using the dealer locator at <http://www.internationaltrucks.com>.

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee as soon as possible.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this campaign.

IF YOU NEED FURTHER ASSISTANCE

If your INTERNATIONAL® dealer is unable to resolve any concerns you have about this campaign, please follow the instructions in the Owner Assistance Guide section of your Owner's Manual or call 1-800-448-7825.

Navistar requests your prompt attention and patience regarding this issue and apologizes for any inconvenience this may cause you.

Navistar, Inc.