CSC-10056165-4743



May 2010

Product Update: Roof Rack Side Rails May Be Cracked

Dear MDX Owner:

This letter is to notify you of a potential problem with your vehicle and what you should do to resolve it.

What is the problem?

On some vehicles with a silver Genuine Acura accessory roof rack, a manufacturing problem may have produced small cracks at the ends of the roof rack side rails. If the side rails are not replaced, the cracks could worsen. This condition affects only silver-colored accessory roof racks installed or purchased before March 15, 2010.

2010 MDX Shown With Silver Acura Genuine Accessory Roof Rack



What should you do?

Call any authorized Acura dealer and make an appointment to have your vehicle repaired. The dealer will replace the roof rack side rails free of charge. Please plan to leave your vehicle for half a day to allow the dealer flexibility in scheduling. If you cannot leave your vehicle for half a day, please contact the dealer to discuss other options.

What to do if you feel this notice is in error

Our records show that you are the current owner of a 2010 MDX that may have had a silver-colored accessory roof rack installed before March 15, 2010. If this is not the case, or the name/address information is not correct, please fill out and return the enclosed, postage-paid Information Change Card. We will then update our records.

If you have questions

If you have questions about this notice, or need help contacting an Acura dealer, please call Acura Client Services at 800-382-2238.

We apologize for any inconvenience this product update may cause you. Our goal is to ensure that your vehicle continues to be as reliable and enjoyable as possible.

Sincerely,

American Honda Motor Co., Inc. Acura Automobile Division

INFORMATION CHANGE CARD VEHICLE IDENTIFICATION NUMBER	Please change	ek the appropria	ta hov an	d make	a any ch	anges o	or correc	tions he	alow	Note: Do no card if inform the bo correc	the ation i x is	
Please check the appropriate box and make any changes or corrections below. Name or Address has changed I no longer own the Acura automobile. It was: Sold (print name and address of new owner below, if known) Exported Destroyed Stolen Lease expired, vehicle returned. The Vehicle ID Number on this card is incorrect. The VIN of my Acura is:												
The vehicle ID N		lis card is inc	T T	ile vii	V OI III	Acui	a 15.				Т	\top
	1.6									iono lo c	noión 1	Ш
Note: Si usted necesita esta información en español por favor comuníquese con Servicio al Client al 800-382-2238 y seleccione la opción 4												
LAST NAME (Apellido) FIRST NAME (Nombre) INITIAL (Inicial)												(Inicial)
ADDRESS NUMBER (Número de dirección) STREET NAME (Nombre de la calle)												
										-		
CITY (Ciudad)					STA	TE (Esta	ido)		ZIP (Cóc	ligo post	tal)	

DETACH THIS STUB BEFORE MAILING



BUSINESS REPLY MAIL

FIRST CLASS

PERMIT NO. 426

GARDENA, CA

POSTAGE WILL BE PAID BY ADDRESSEE:

American Honda Motor Co., Inc. P.O. BOX 2215 Torrance, California 90509-9870



