

If the MVCI displays **This vehicle does not need an update at this time** during the update, the software for this service bulletin is already installed.

Year/Model	Program ID (or later)	Program P/N (or later)
2007 MDX	YEA590	37805-RYE-A59

**REPAIR PROCEDURE**

1. Update the PGM-FI software. Refer to Service Bulletin 01-026, *Updating Control Units/Modules*.
2. Center-punch a completion mark above the first character of the engine compartment VIN:



3. **For California Residents Only:** Fill out a Vehicle Emissions Recall - Proof of Correction certificate, and use **R91** as the recall number. Give the certificate to your client, and advise him or her to keep it as proof that the product update was completed. Your client will need to submit the certificate to the DMV only if the DMV requests it. If you need more certificates, use reorder number **Y0657**.

*Example of Client Letter*

September 2011

**Product Update: MIL Comes On With DTC P0420**

Dear MDX Owner:

This letter is to notify you of a potential problem with your vehicle and what you should do to resolve it.

**What is the problem?**

On some 2007 MDXs, the rear warm-up three-way catalytic converter can be damaged under certain driving conditions.

**What should you do?**

Contact any authorized Acura dealer for an appointment to have your vehicle's software updated. The dealer will update the software in the powertrain control module. This work will be done free of charge. Please plan to leave your vehicle at the dealer for half a day to allow them flexibility in scheduling.

**California Residents** - After doing the update, your dealer will give you a Proof of Correction certificate. Keep this certificate for your records as proof that the product update was completed. Submit the certificate to the DMV only if the DMV requests it.

**What to do if you feel this notice is in error.**

Our records show that you are the current owner or lessee of a 2007 MDX involved in this campaign. If this is not the case, or the name/address information is not correct, complete, sign, and return the enclosed, postage-paid Information Change Card. We will then update our records.

If you previously paid to have the rear warm-up three-way catalytic converter replaced, you may be eligible for reimbursement, even if you no longer own the vehicle. Refer to the attached Instructions for Reimbursement form for eligibility requirements and the reimbursement procedure.

**Lessor Information**

If this is a leased vehicle, and the lessor/registered owner received this notice, please forward a copy of this notice to the lessee.

**If you have questions**

If you have any questions about this notice, or need assistance with locating an Acura dealer, please call Acura Client Relations at 800-382-2238, and select option 4.

We apologize for any inconvenience this campaign may cause you.

Sincerely,  
**American Honda Motor Co., Inc.**  
**Acura Automobile Division**