



Can-Am Roadster Product (Shop Talk)

[Reply](#) [Topic Options](#) ▾

[◀ Message Listing](#) [◀ Previous Topic](#) [Next Topic ▶](#)

DanyD

BRP Service Dept - N/A



Posts: 970
Registered: 10-19-2011
Location: NA

[Report Inappropriate Content](#)
Message 1 of 8 (179 Views)

2015-1 Warranty Bulletin - Oil Sweating from Clutch Cover HCM Connector (SE6) [New]

[Options](#) ▾

3 weeks ago

Newly released in the BOSSWeb home page messages is a warranty bulletin for RT and F3 models with SE6 transmission. Seems the plastic nut securing the HCM harness connector to the clutch cover was not torques properly. Simple fix - retorque the nut. Try to get these done at PDI as much as possible as the consequences are possible oil sweating past the o-ring.

To know if a unit is eligible for the bulletin simply enter the VIN in the Knowledge Center and check the warranty section on the VIN information page RH side.

Refer to [ROADSTER 2015-1 Oil Sweating from Clutch Cover HCM Connector \(SE6\)](#) for all the details.

Dany D
Roadster Product Specialist

[Me too](#)

Everyone's Tags: [2015-1](#) [View All \(1\)](#)
[Add Tag...](#)

4 Kudos [+ ★](#) [Reply](#) [Quick Reply](#)