



**CSC-10043867-3747**

A **PACCAR** COMPANY

Date

Customer Name

Customer Address

Subject: Kenworth campaign E050 – C1166

Dear Kenworth Customer,

Kenworth has determined that certain vehicles equipped with PACCAR PX-6 and PX-8 engines manufactured between May 15, 2009 and March 11, 2011, will benefit from recalibration of the Engine Control Module (ECM). The vehicle(s) identified by VIN on this letter is (are) subject to this campaign repair.

Left uncorrected, it is possible that your vehicle operator's dash display will show erroneous fault codes or check engine lamp warnings related to the exhaust aftertreatment system and NOx emissions measurement.-

We encourage you to schedule for repairs as soon as possible. Please contact your authorized PACCAR Engine dealer or Cummins Distributor for an appointment. Repairs will take less than hour and will be performed at no cost to you if completed by January 1, 2014\*.

If contacting a PACCAR dealer to perform this work, please refer to campaign E049. If contacting a Cummins Distributor, refer to campaign C1166.

We apologize for the inconvenience this may cause and appreciate your cooperation in this matter.

Thank you,

Mike Kalkoske  
Director, Quality Services  
Kenworth Truck Company

*\* This campaign repair includes software updates which may change with time. The program and expiration date may be subject to revision.*