



October 31, 2012

Dear Blue Bird Owner,

The service brake switch on certain 2013 model year propane Vision model buses equipped with Ford 6.8L engines may not have been installed and adjusted correctly which may cause the stop lights to remain on without the service brakes applied.

To correct this condition a new brake switch mounting bracket is available. To facilitate installation of the new brake switch mounting bracket a new brake switch will also be provided.

Your bus(es) affected by Service Bulletin S12VM are identified by Blue Bird body number(s) under section 2 on the enclosed cover sheet.

You may contact your Blue Bird dealer to arrange to have Service Bulletin S12VM performed. Or, if you prefer, you may perform Service Bulletin S12VM yourself or have a qualified repair facility convenient to you perform this service bulletin. A qualified technician should perform Service Bulletin S12VM.

Parts for Service Bulletin S12VM must be ordered through your usual Blue Bird Service parts source. Parts are anticipated to be available on or about November 07, 2012.

Time to perform Service Bulletin S12VM is 0.5hr (30 minutes) per bus.

Service Bulletin S12VM ends one (1) year from date of issue. Claims for repairs performed after the end date cannot be submitted to Blue Bird.

Should you have any questions concerning this bulletin, please contact your Blue Bird dealer.

Sincerely,

Bill Coleman
Engineering Services
478-822-2242
bill.coleman@blue-bird.com

BLUE BIRD BODY COMPANY

P.O. Box 937 – 402 Blue Bird Blvd – Fort Valley, Georgia – (478) 825-2021