



CSC-10048439-8593

A **PACCAR** COMPANY

Date

Customer Name

Customer Address

Subject: E061 PACCAR MX Engine Software Update

Dear Kenworth Customer,

Since the introduction of the PACCAR MX Engine, PACCAR has continued to monitor field performance of the engine to ensure customer satisfaction. As a result of our monitoring, we have developed performance enhancements which have been included in current product and which can be incorporated into engines already in service by means of control unit software updates.

Most notable improvements of current software updates impact the engine turbocharger and emission measurement/control systems to reduce soot buildup with associated engine warning lamp events and the possibility of engine derate. This, and other updates that may have been implemented since the purchase of your vehicle, will result in more efficient engine performance and Kenworth is anxious to implement these updates on your vehicle.

Please contact a Kenworth dealership to schedule an appointment for this work. You can find the nearest Kenworth dealer at Dealer Locator on the website www.Kenworth.com.

When contacting your selected Kenworth dealer, refer to campaign E061 and the VIN listed on this letter. The repair will take approximately one and a half hours* and there will be no charge to you for this work.

We apologize for the inconvenience but ask for your cooperation to ensure continued satisfaction with Kenworth products.

Thank you,

Mike Kalkoske
Director, Quality Services
Kenworth Truck Company

* Additional product improvements have been implemented since introduction of the PACCAR MX engine and your vehicle may be eligible for other no-charge updates. Your selected Kenworth dealer will advise you if this is the case.

VIN: