



CSC-10049801-3962

Date

Customer Name

Customer Address

Subject: TIB 45-045, Bendix ACom for Prototype CNG Engines

Dear Kenworth Customer,

Kenworth has identified that first chassis built with ISX engines and CNG fuel systems did not have compatible software programs between the Bendix ABS electronic control module and the Cummins Engine electronic control module. The result is that your vehicle does not have the most efficient deployment of the Automatic Braking System (ABS) coordinated with the engine brake.

The chassis listed by VIN on this letter is included in this population and Kenworth would like the opportunity to correct this condition.

Please contact a Kenworth dealership to schedule an appointment for this work. You can find the nearest Kenworth dealer at Dealer Locator on the website www.Kenworth.com.

When contacting your selected Kenworth dealer, refer to campaign TIB 45-045 and the VIN listed on this letter. The repair will take approximately half an hour and there will be no charge to you.

We apologize for this inconvenience but ask for your cooperation to ensure continued satisfaction with Kenworth products.

Thank you,

Mike Kalkoske
Director, Quality Services
Kenworth Truck Company