

Welcome to the new ElsaWeb Newsletter

This newsletter will be a weekly email written for technicians to update you on all things new in ElsaWeb. The newsletter will be sent out at the beginning of the week to inform you of changes made to ElsaWeb in the previous week. It will include sections for ElsaWeb related news, a summary of feedback status and feedback updates, highlights/tips from the previous weeks' changes and summary tables of the information that has changed in the past week, this may include technical bulletins, campaigns, RVU's, wiring diagrams, repair manuals, & labor operations). We from the Service Information team hope that you find this information useful and valuable.

Feedback Corner

In the Feedback Corner, each week will have a weekly status of open ElsaWeb feedback and a highlighted feedback. The feedback of the week is from John, regarding a 2012 Audi A6 Sedan (4G2). He says:

"It is not listed in center console removal and installation that you must disconnect the driver side and passenger side LED light strips before attempting to remove the console. Failure to do so will result in a damaged harness and/ or housing."

A technical editor reviewed this feedback and verified the concern with the factory. The repair manual has been updated to reflect the changes. John included his full name and email with the feedback and will receive Audi Winners Circle rewards for helping improve the quality of the repair information.

Photo of the Week



Feedback Status			
New	Completed	In Progress	To Factory
50	14	28	8

*Please note, this feedback feature is not the place to obtain technical assistance on Audi vehicles, nor to report potential issues you may have experienced with a vehicle. If you require assistance in repairing or diagnosing a vehicle issue, or wish to report a technical issue, please create a Audi Technical Assistance ticket and contact the Audi Technical Assistance at (800)-678-2389.

Suggestions

Please send any comments or suggestions to: aoa. WorkshopInformation@audi.com

© 2012 Audi of America, Inc.



	Repair Manuals, Wiring Diagrams, and Labor Operations			
ELSA Name	Model	Repair Manuals	Wiring Diagrams	Labor Operations
8PA	A3 (2006 >)	Engine Mechanical (CBAA, CBAB, CBBB, CBEA)		
4B2, 4B4	A6, RS6 (1998-2004)	Body Exterior		
4B5	A6 Avant (1999-2004)	Body Exterior		
4BH	A6 allroad Quattro (2001-2005)	Body Exterior		
4B6	S6 Avant (2002-2003)	Body Exterior		
4G2	A6 Sedan (2012 >)	Body Interior		
4H8	A8 L (2011 >)		Component Locations: Models routing	
422	R8 GT (2012 >)		Component Locations: Relay	
423	R8 (2008 >)		Component Locations: Ground Connections Component Locations: Fuses Component Locations: Control Modules Component Locations: Connector stations and connectors of wiringharnesses	
427	R8 GT Spyder (2012>)			
429	R8 Spyder (2011 >)			
8RB	Q5 (2009 >)		Component Locations: Transmission Systems Component Locations: Anti-Lock Brake Systems	

Campaigns

No new additions to ElsaWeb this week.

RVU's

No new additions to ElsaWeb this week.

© 2012 Audi of America, Inc.



Technical Bulletins

Title: 94 Small mark in the headlight lens

Published: August 24, 2012 Instance No: 2023014/2

Condition: With the hood open, a line or mark is observed in the headlight lens, mainly at the curved portion of the lens, beginning at the top of the black housing and extending a short distance. This line or mark cannot be seen if the hood is fully closed.

Model(s)	Year	Vehicle-Specific Equipment
A3	2009 – 2013	Not Applicable

Title: 01 MIL on DTC P00AF Stored in ECM Fault Memory

Published: August 24, 2012 Instance No: 2030609/1

Condition: MIL on DTC P00AF Stored in ECM Fault Memory.

Model(s)	Year	Vehicle-Specific Equipment
A3 2.0 TDI FWD	2013	CBEA Engine Code

Title: 45 DTC entry in Sensor Electronics (3B) "B200000 control unit faulty"

Published: August 24, 2012 Instance No: 2027341/2

Condition: The DTC entry "B200000 control unit faulty" is stored in

address word 3B for Sensor Electronics.

Model(s)	Year	Vehicle-Specific Equipment
A8	2011 – 2013	
A7	2012 - 2013	Not Applicable
A6	2012 - 2013	

Title: 37 Transmission shudders on acceleration

Published: August 24, 2012 Instance No: 2022600/3 Condition:

-Vehicle shudders when pulling away. The vehicle pulls away from a

stop with a delay and a shudder.

- Shuddering on acceleration from under 15 mph.

- The complaint can be reproduced, but no fault can be found.

Model(s)	Year	Vehicle-Specific Equipment
A4/A5	2009 – 2010	2.0 TFSI and 0AW Gearbox

© 2012 Audi of America, Inc.



Title: 17 Engine oil consumption too high, 3.0T TFSI Model Year 2010 - 2012

> Published: August 24, 2012 Instance No: 2030197/2

Condition: Based on customer complaint, follow the procedure below:

Model(s)	Year	Vehicle-Specific Equipment
S4, S5 Cabriolet	2010 – 2012	ССВА
Audi Q7	2011 - 2012	CJWC, CJWB, CJWE
A6	2010 – 2011	CCAA
A6/A7	2012	CGXB

Title: 57 Remote key malfunction - Repair Authorization

Published: August 24, 2012 Instance No: 2024463/5 Condition:

- One of the following conditions is present:

- Keyless entry is inoperative.
 - Remote range is poor.
- Audi Advanced key is inoperative.

Model(s)	Year	Vehicle-Specific Equipment
All Audi	2013	Not Applicable

Title: 64 Noise when operating front window

Published: August 24, 2012 Instance No: 2030561/1

Condition: The customer may report grinding or squeaking noises when

operating the front door windows up/down

Model(s)	Year	Vehicle-Specific Equipment
A8	2009 – 2010	Not Applicable

Title: 66 License Plate Mounting Bracket Threaded Inserts
Stripped

Published: August 24, 2012 Instance No: 2030471/1

Condition: Customer may report the license plate attachment screws do

not install properly.

Model(s)	Year	Vehicle-Specific Equipment
А3		
A4		
A5/A5 Cabriolet		
A6		
Α7	2012 – 2013	Not Applicable
A8	2012 - 2013	Not Applicable
Audi Q5		
Audi Q7		
R8		
TT		

© 2012 Audi of America, Inc.