



Service Bulletin

File in Section: -

Bulletin No.: PI0817

Date: September, 2012

PRELIMINARY INFORMATION

Subject: Engine Cranks and Will Not Start

Models: 2007-2010 Chevrolet Cobalt
2007-2010 Pontiac G5
2007 Saturn ION
Equipped with 2.2L Engine RPO NU6

Condition/Concern

Some customers may comment that the engine cranks but will not start.

Recommendation/Instructions

When diagnosing an engine crank/no start condition and it is determined that the fuel pump wire harness connector needs to be replaced, the wiring harness connector is now available for service separately. It is no longer necessary to replace the complete fuel pump cover assembly (fuel pump flange).

Parts Information

Part Number	Description
19119198	Wiring Harness Connector

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
N6652	Connector with Leads Assembly Replacement	Use Published Labor Operation Time