



Service Bulletin

File in Section: -

Bulletin No.: PI0819

Date: September, 2012

PRELIMINARY INFORMATION

Subject: Fuel Display is Slow to Show Accurate Reading After Fill Up

Models: 2012-2013 Chevrolet Sonic

Condition/Concern

Some customers may comment that the fuel gauge is slow to display the accurate fuel amount after fill up. This is a normal condition when customers are leaving the vehicle running or the ignition key turned on during fill up.

Recommendation/Instructions

Verify that the concern is not being induced by the customer leaving the vehicle running while filling up the fuel tank.

Important: DO NOT REPLACE ANY COMPONENTS FOR THIS ISSUE.

Customer Information

Please communicate to the customer on the importance of not filling the fuel tank while the engine is running and that this condition is a normal operating characteristic of their vehicle.

It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.