



Service Bulletin

File in Section: -

Bulletin No.: PIC5287C

Date: December, 2012

PRELIMINARY INFORMATION

Subject: Fog Lamp Operation or Adding / Enabling Fog Lamps On a Vehicle Not Originally Equipped with Fog Lamps

Models: 2010 - 2013 Chevrolet Camaro

This PI was superseded to update model years and reword title. Please discard PIC5287B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Condition 1:

Some customers may comment that their vehicle's fog lamps are inoperative. Further vehicle inspection will identify that the vehicle is equipped with the HID Headlamps (RPO T4F). Vehicles equipped with HID headlamps (RPO T4F) have DRLs in place of the fog lamps.

Condition 2:

Some customers may request to have Fog Lamps added or enabled on a vehicle that was not originally built with fog lamps.

Recommendation/Instructions

Correction 1:

This is a normal operating characteristic. No repairs are recommended.

Correction 2:

There is not a GM approved fog lamp kit that can be installed on a Camaro not originally equipped with that feature. Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.