



Service Bulletin

File in Section: -

Bulletin No.: PIC5320B

Date: December, 2012

PRELIMINARY INFORMATION

Subject: Adding Radio Steering Wheel Control Switch (RPO NZL)

Models: 2010 - 2013 Chevrolet Camaro

This PI was superseded to update model years. Please discard PIC5320A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may inquire if it is possible to install steering wheel mounted audio controls on a vehicle that was not originally built with that option.

Recommendation/Instructions

It is possible to install audio Steering Wheel Controls (SWC) at the customer's expense. This modification will require installation of the appropriate right hand steering wheel control switch, steering wheel pad accessory harness, and re-calibration of the BCM. You will need to contact Techline Customer Support Center (TCSC) for a VCI number to recalibrate the BCM. Since this is not a warrantable repair, TCSC will charge a fee for this service. Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.