



Service Bulletin

PRELIMINARY INFORMATION

Subject: Power Folding Top Diagnostic Tips

Models: 2011 - 2013 Chevrolet Camaro
Convertible Models Only

This PI was superseded to update recommended field and model years. Please discard PIC5610B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

In an effort to aid in creating a quick diagnostic approach to customer concerns regarding the convertible roof top the following PIs have been compiled here. They are listed in no specific order.

Recommendation/Instructions

Important: This PI in no way eliminates the need to perform regular SI searches for newly released or revised documents specific to the customer concern. It is written as a quick reference only. Reference the latest version of each of the following to aide in diagnostics / repair:

#12052: Customer Satisfaction - Convertible Top Enhancements

#PIC5609: Side Tension Cable Visible When Top Is In Stowage Compartment

#PIC5608: Oil Canning Or Pop Noise In Rear Seat Area

#PIC5605: Folding Top Pulls Loose From Rear Side Rail

#PI0625: Hydraulic Pump Leaking Fluid in Area of Rear Seat, Floor or Trunk, Convertible Top Inoperative or Noise

#PIC5449: Convertible Roof Cloth Sags At Rear / Large Gap Between Number 5 Bow And Rear Panel

#PIC5458: Water Leak In Rear Floor Area

#PI0406: General Guidelines for Inspection of Convertible Water Management Bag Anytime Folding Top is Removed

#PIC5553: Creak Or Squeak Noise From Rear Of Folding Top

#PI0351: Folding Top Tonneau Cover - Installation of Body Side Lower Trim Panel Spacer During Pre-Delivery Inspection (PDI)

#PIC5527: Headliner Trim Cloth Pulls Loose From Rear Window Retainer

#PI0525: Folding Top Striker Assembly Plastic Insert Loose/Missing

#PI0520: Top Not Secure Message Displayed in Driver Information Center (DIC)

#PI0509: Convertible Top Will Not Open/Retract, Clear Top Storage Area Message Displayed in Driver Information Center (DIC)

#PI0449: Rattle from Rear Compartment Area when Driving with Convertible Top in Closed (Up) Position

#PI0424: Rattle, Creak or Popping Noise in Rear Floor Area

#PI0397: Water Leak in Rear Compartment/Trunk - Convertible Top Water Management Bag Repair

#PI0379: Information on Location of Convertible Specific Manual Trunk Release

#PI0378: Information on Convertible Top Operation Below 0C (32F) in Snow, Rain or After Wet Conditions - Ice Formation in Water Management Bag

#PIC5724: Side Tension Cables Are Visible After Folding Top Replacement

#PI0756: Retrofit Procedure for New Corded Folding Top Cover Installation to Original Design Frame

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the

remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION