



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** DTC C056D Set In Steering Wheel Angle Sensor

**Models:** 2013 Cadillac ATS

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

In rare instances, a technician may notice a DTC C056D set in the Steering Wheel Angle Sensor (SAS) even though the vehicle was in for repair for something unrelated to this component.

### Recommendation/Instructions

**Important:** Do not replace the SAS until further diagnosis is performed.

A condition exists in which the SAS may falsely set a C056D whenever DTCs are retrieved from the vehicle.

- If the vehicle is in for service(s) unrelated to the SAS and its operation, the DTC should be ignored.
- If the vehicle is in for service(s) related to the SAS and its operation, follow published diagnostic procedures and repair/replace as necessary.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION