



Service Bulletin

PRELIMINARY INFORMATION

Subject: Squawk Or Grunt Noise On The 2-3 Shift

Models: 2008-2009 Chevrolet Avalanche, Suburban, Tahoe
 2008-2012 Chevrolet Colorado
 2008-2013 Chevrolet Express, Silverado
 2008-2009 Chevrolet Trailblazer, Trailblazer SS
 2008-2012 GMC Canyon
 2008-2009 GMC Envoy
 2008-2013 GMC Savana, Sierra
 2008-2009 GMC Yukon, Yukon XL
 2008-2009 Hummer H3
 2008-2009 Saab 9-7X, 9-7X Aero
 Equipped with 4L60E, 4L65E or 4L70E (RPO - M30, M32 or M70) Transmission

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customers may comment that the transmission makes a squawk or grunt type noise when shifting from 2nd to 3rd gear.

Recommendation/Instructions

The 3-4 clutch Friction (654A) and Steel (654B) Clutch Plates along with the Apply Plate (653) and Selective Backing Plate (655) should be replaced.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
K7252	3-4 Clutch Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION