



Service Bulletin

PRELIMINARY INFORMATION

Subject: Content Theft Alarm Inoperative

Models: 2007-2013 Chevrolet Silverado
2007-2013 GMC Sierra
Without YE9 or Y91

This PI was superseded to update model years. Please discard PIT4357F.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some owners may comment that the content theft alarm is inoperative. The vehicle must have RKE Keyless Entry (RPO AU0/AU3) AND RPO YE9 or Y91 to be equipped with content theft alarm.

Note: The window sticker, under standard Safety and Security, will indicate that Theft Deterrent System is standard equipment. This is in reference to the PassKey III+ and is not meant to include or imply Content Theft Deterrent system.

Recommendation/Instructions

No repairs should be made as this is normal.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION