



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Part Availability of Missing Screw(s) For Front Fascia And/Or Air Deflector

**Models:** 2013 Cadillac ATS

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A technician may find in rare cases a screw missing from the front fascia or air deflector and have difficulty finding the replacement part number in the GM Electronic Parts Catalog (EPC).

### Recommendation/Instructions

Please order the quantity of screws required as called-out in the Part Information section.

### Parts Information

Part Number	Description	Qty
11570637	Screw	As Needed

The GM EPC will soon be revised to reflect this information. This PI will be cancelled once that occurs.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION