

Service Bulletin

PRELIMINARY INFORMATION

Subject: 2009-2013 ABS/ESC Module Restriction Part Numbers 95241314 and 95242007

Models: 2009-2013 Chevrolet Aveo 2009-2010 Pontiac Wave, G3 2007-2012 Chevrolet Optra

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

As part of our ongoing quality improvement efforts, the 2009-2013 ABS/ESC Module part numbers 95241314 and 95242007 will be placed on restriction through the PQC to assist Engineering with product feedback.

Important: Dealers cannot order P/N 95241314 and 95242007 for stocking their inventory. Your cooperation with this program is greatly appreciated.

Important: Prior to contacting the PQC please fill out the information listed below as accurately as possible.

Recommendation/Instructions

Caller's Name/Position:

Technicians Direct Phone:

What is the Customer's concern:

- Did you perform the ABS/ESC module Test per PRODUCT SAFETY RECALL 12189? If "No" - STOP - advise caller to perform the ABS/ESC module Test and call back. If "Yes" Continue.
- 2. Did the ABS/ESC module pass all 4 procedure tests (i.e. 4 pedal drops and 4 push backs are "YES")?
 - If "Yes" (all 4 procedure tests passed) STOP No part is required. Please follow the system bleed procedure detailed in the PRODUCT SAFETY RECALL 12189.

If "No" (all 4 procedure tests did NOT pass), ask the caller which step did NOT pass (i.e. 1, 2, 3, or 4) and document. Continue.

Did you run the complete procedure more than 1 time on the vehicle?
If "Yes", performing the procedure twice could provide inaccurate results.
Only the first results should be used to determine HCU replacement.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION