



Service Bulletin

PRELIMINARY INFORMATION

Subject: Normal Characteristic - IPC Menu And Reset Button Inoperative for Trip Odometer

Models: 2013 Chevrolet Sonic

Condition/Concern

A dealer technician or customer may comment that the Menu and Reset buttons for the Trip Odometer is inoperative or will not change.

Recommendation/Instructions

Important: Do NOT replace or program any components for this concern.

The following changes were made for the 2013 model year:

- ⇒ The Trip Odometer was moved next to the Odometer
- ⇒ The Trip Reset Button on the IPC must be used to toggle and reset the Trip Odometer

Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION