



Service Bulletin

PRELIMINARY INFORMATION

Subject: Water Leak In Trunk

Models: 2008- 2013 Cadillac CTS Models
2005- 2011 Cadillac STS Models

This PI was superseded to update model years and warranty information. Please discard PIC5004A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment that water drips out of the trunk decklid from behind the trim panel. The cause may be water entering the decklid past one or both of the license plate grommet's foam gaskets (1).



Recommendation/Instructions

Seal the license plate grommets. A suggested sealer for this repair is Kent Automotive High-Tech P10200 Clear 5 Fl. Oz. Tube Grade.

Parts Information

excel sheet

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
B5410	Body Joint Resealing	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the

remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION