



Service Bulletin

PRELIMINARY INFORMATION

Subject: Full Heat From Vents After Restart and/or Heated Seats Do Not Turn On

Models: 2013 Chevrolet Malibu

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer or technician may indicate that intermittently when the vehicle is started, there is unwanted full heat from the vents and/or the driver or passenger heated seat will not come on when the respective switch is depressed.

Recommendation/Instructions

Using SPS, select: ECC Remote Heater and Air Condition Control Module - Programming.

Once completed, select: ECC Remote Heater and Air Condition Control Module - Setup.

Evaluate performance of both systems to validate the repair.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
D4707	Electronic Climate Control Module Programming	0.3 hr

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION