

Audi ElsaWeb Newsletter

Edition 5: October 1, 2012

Content

- [Audi Dealer Meeting Winners](#)
- [Feedback Corner](#)
- [Technical Bulletins](#)
- [Campaigns](#)
- [Updates](#)
- [Repair Manuals](#)
- [Wiring Diagrams](#)
- [Suggestions](#)



Audi Dealer Meeting Winners

Last week in San Diego, California, at the Audi Dealer Meeting, there were two winners for the iPad drawing. The first winner is Joe Sparacino, General Manager of Audi Pembroke Pines in Pembroke Pines, Florida, The second winner is Shannon Greenwood, Service Manager at Thelen Audi in Bay City, Michigan. Congratulations Joe and Shannon!

[Back to top](#)

Feedback Corner

This week's feedback is from Allan regarding TSB 17 Engine Oil Consumption too High, 3.0T TFSI 2010-2012. He says:

"When performing the replacement of the pressure valve underneath the intake; there is a coolant pipe that needs to be removed to gain access to the bolts for the valve. There should be instructions to place something to capture the coolant so the valley doesn't fill up. Second there should be additional parts listed to replace the O-ring on the end of the pipe and add time units for labor ops for additional

time for coolant drain and refill."

The Service Information team reviewed this feedback and verified the concern with the Technical Bulletin. The parts list was adjusted accordingly to add the O-ring to the Technical Bulletin. Allan included his full name and email address with the feedback and will receive Audi Winners Circle Rewards for helping improve the quality of the repair information.

Feedback Status		
New	Completed	To Factory
19	19	5

*Please note that this feedback feature is not the place to obtain technical assistance for Audi vehicles, or to report potential issues you may have experienced with a vehicle. If you require assistance in repairing or diagnosing a vehicle issue, or wish to report a technical issue, please create an Audi Technical Assistance ticket and contact the Audi Technical Assistance at (800)-678-2389.

[Back to top](#)

Technical Bulletins

01 MIL on, no leak in EVAP system (DTC P045600 in ECM)		
Model(s)	Year	Vehicle-Specific Information
A8	2011	4.2L Engine
A6	2012	3.0L Engine
A7	2012	3.0L Engine
• MIL on. • DTC P0456 (very small EVAP leak) stored in ECM. • No leaks found in the EVAP system.		

57 Outer door seals loose		
Model(s)	Year	Vehicle-Specific Information
A4	2011-2013	All
Q5	2011-2013	All
The outer door seals have become partially detached		

91 MMI 3G+ Various Technical Issues (K0566 Update)		
Model(s)	Year	Vehicle-Specific Information
A6	2012	MMI 3G+
A7	2012	MMI 3G+
A8	2011-2012	MMI 3G+
Q7	2012	MMI 3G+
This bulletin only applies to vehicles with Navigation Plus (PR Number 8DY). The applicable vehicles can be clearly identified by the SIM card slot on the faceplate of the front MMI main unit.		

90 Topview/Cornerview camera does not work, PR No. KA4 or KA6 - A6, A7, A8		
Model(s)	Year	Vehicle-Specific Information
A6	2013	Topview/ Cornerview
A7	2013	Topview/ Cornerview
A8	2013	Topview/ Cornerview
The Topview camera system is inoperative. No camera images are displayed. The acoustic parking system functions normally.		

90 Sporadic malfunctions during MMI 3G+ complaints		
Model(s)	Year	Vehicle-Specific Information
A6	2012	MMI 3G+
A7	2012	MMI 3G+
A8	2011-2012	MMI 3G+
When driving, various warning lights come on, sometimes with restricted functions in the electric system. These complaints only occur together with complaints or a failure of the MMI 3G+ infotainment system.		

[Back to top](#)

Campaigns

No new Campaigns in ElsaWeb.

[Back to top](#)

Updates

No new Updates in ElsaWeb.

[Back to top](#)

Repair Manuals

Repair Manuals				
Elsa Name	Model	Book Updated	Engine Code	Reason
4G	A6 2011> A7 2012>	Fuel Supply System	CGXB,CAEB,CEUC,CHJA	Feedback# 614088
4G2, 4GA	A6 2011> A7 2012>	Maintenance Procedures	All	Feedback# 616698
8J	TT 2007>	S tronic Transmission	All	Feedback# 585809
8T3	A5/S5 2008>	Electrical Equipment	Multiple	Feedback# 616793
4G, 4H	A6 2011> A7 2012> A8 2010>	Generic Scan Tool	CEUC,CEUA,CGTA	Factory Update

[Back to top](#)

Wiring Diagrams

Wiring Diagrams		
Elsa Name	Model	Book Updated
8F	A5 Cabrio 2010–2013	• Standard equipment, from August 2011 • Convenience system, from August 2011 • Airbag systems, from August 2011 • 4.2L gasoline engine, CFSA, from May 2012 • 3.0L gasoline engine, CGXC, from August 2011 • 2.0L gasoline engine, CPMA, from October 2011
8K	Audi A4 2009– 2013	• Standard equipment, from November 2011 • Comfort system, from November 2011 • Automatic transmission 7-speed 0B5 (S tronic), from September 2008 • Airbag systems, from November 2011 • 4.2L gasoline engine, CFSA, from May 2012 • 3.0L gasoline engine, CGXC, from November 2011 • 2.0L gasoline engine, CPMA, from November 2011

[Back to top](#)

Suggestions:

Please send comments or suggestions to: aoa.WorkshopInformation@audi.com

[Back to top](#)

© 2012 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.