

Technical Service Bulletin



91 Dash insert, air conditioning control panel or inside light flickers

91 12 63 2021151/4 October 4, 2012. Supersedes Technical Service Bulletin Group 91 number 11 – 83 dated April 15, 2011 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All Audi	2006 – 2013	All	PR 8GH

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised header data (Added model years)
3	4/15/2011	Revised header data (Added model years)
2	8/9/2010	Revised header data (Controlling TSB display in ElsaWeb)
1	7/20/2009	Original publication

The customer may report that the illumination of the dash insert, the air conditioning control panel or the inside light flickers when briefly pressing the accelerator in P or N or when shifting down while driving downhill.

Technical Background

Only vehicles with PR number 8GH may be affected.

When high electricity consumers are switched off and the battery is fully charged, the energy generated by the alternator is sometimes too great for the power system to absorb. This may lead to briefly increased voltage, and the lights mentioned above may briefly flicker.

This characteristic is caused by the alternator design and is a normal condition of the vehicle.

Production Solution

No change.

Service

Repairs and parts replacements do not change the above characteristic. Explain to the customer that this phenomenon is not a malfunction.

Technical Service Bulletin



Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.