

10/26/2012

Safety Bulletin Notification XLR10242012

Dear Forest River Customer,

Forest River XLR division has issued this safety bulletin to address the possibility that there may be improper spacing of the supports for the black iron pipe manifold in the area of the suspension only on the following models XLF35X10, XLF35X12, XLF35X14, XLF380AMP, XLF395AMP AND XLF395AMP12 built from October 29, 2009 to present.

Please make an appointment with your dealer or service center to have the supports for the black iron pipe inspected. There should be a space of no less than ¼" horizontally between the black iron pipe manifold and the end of the shackle bolt in the suspension area.

If there is insufficient spacing your dealer or service center will contact Diana Daly at XLR Warranty and Service 574-975-0292 or email her at ddaly@forestriverinc.com and ask for the spacer kit for service bulletin XLR10242012, this repair, if needed, will be done at no cost to you, the customer.

If you have any questions please contact Diana Daly at the previously mentioned telephone or email address.

Forest River is dedicated to the quality and safety of its products and regret any inconvenience this may cause.

Sincerely

XLR Warranty and Service