

Local Campaign Request Form

Rev3_March 2013

<i>Request #</i>		<i>Payer</i>	<u>Bulletin</u>
<i>Other Reference</i>	NYCT Campaign# ...		

To be filled by Requester

<i>Title</i>	Install washers on front passengers modesty panel to increase gap between hand rail and panel		
<i>Customer (s) involved</i>	NYCT		
<i>Comments</i>	No enough clearance between rub rail and modesty panel, this campaign is to add spacer to increase the gap to what is required.		
<i>Ref to procedure</i>	Power point from Engineering, no assistance from Pub is required		
	 Pièce jointe	 Pièce jointe	 Pièce jointe
<i>Time Allocated (hr)</i>	1 hrs/vehicle		
<i>Parts involved</i>	502768 (8)		
	http://portal.scr.volvo.net/sites/vbc-scr-dtr-service/Service%20tips/Technical%20Publications/MTA%20X3%20Multiplex.ppt		
<i>Causal p/n</i>	(Should be Rubrail P/N) Not applicable, no failure only spec not met		
<i>Est. Cost per vehicle (at selling price)</i>	1hrs @\$115 and (8)*\$1.49 for washers \$130/vehicle		
	 Pièce jointe	 Pièce jointe	 Pièce jointe
<i>Qty of vehicles involved</i>	90 vehicle involved		
<i>Total cost of campaign (cad)</i>	\$11,700.00		
<i>List of equipments</i>	All of NYCT fleet of 90 vehicles		

Type of Info ?

- ☐ Please keep bulletin and notification internal (SP-type of bulletin)
- ☐ Please make sure procedure is publically available on our websites... (WB)

Comments

 Pièce jointe

 Pièce jointe

 Pièce jointe

To be filled by Warranty

Fail Code

18.02

Defect Code

09

System Condition

Supplier Recovery

Part Disposition

Comments

To be charged to System Condition B. Please confirm Causal P/N...

 Pièce jointe

 Pièce jointe

 Pièce jointe

To be filled by Tech Pub

Publication #

SP12-318

VBC Bulletin #

Cost Approval Date

2012-11-01

Notif Create Date

2012-11-05

Comment

 Pièce jointe

 Pièce jointe

 Pièce jointe